



Production

MINING



- 1 Stripping**
Provides access from the surface to the deposit through underground workings used to transport mined ore, people, etc.
 - 2 Development workings**
The deposit is divided into separate sections, including mining levels, blocks, sublevels, stoops, etc.
 - 3 Stopping**
 - separation of ore from the rock;
 - delivery of ore from the mine face to the haulage level;
 - maintenance of the excavated area.
 - 4 Rock mass removal**
Ore is removed by load-haul dumpers and delivered to the surface by conveyor, railway and motor vehicles, or through skip shafts.
- To the concentrators

ENRICHMENT




Ore mined at Nor Nickel's deposits are uniquely rich

STRATEGIC PRIORITY:



Major upgrade of production capacities

NICKEL PRODUCTION



COPPER PRODUCTION

